

H PARTS LIST

HT™ SERIES HT300YB SUSPENSIONS

LIT NO: L1271

DATE: April 2023

REVISION: B




HT300YB PARTS LIST



Picture shown may not resemble all models.

HT300YB





HT300YB PARTS LIST

ITEM	DESCRIPTION	PART NO.	QTY.	NOTE
1	BEAM ASSEMBLY			
	Standard, roadside, QUIK-ALIGN®	S-31377-3	1	
	Standard, curbside, QUIK-ALIGN	S-31377-4	1	
2	BUSHING ASSEMBLY	S-30862	2	
3	TUBE SLEEVE	S-7342	2	
4	ALIGNMENT COLLAR			
	4a Eccentric washer, QUIK-ALIGN	S-20925	2	Bolt hole is offset from center of collar
	4b Concentric washer, QUIK-ALIGN	S-20924	2	Pivot bolt hole is center of collar
5	BUSHING TUBE SPACER	S-21099	4	
6	QUIK-ALIGN PIVOT BOLT KIT	S-25948	2	Includes shear-type bolt, nut & washers
7	U-BOLT KIT, RD	S-3650/4	4	
8	TRI-FUNCTIONAL® II BUSHING KIT	S-26000	2	Includes bushing assembly, bushing tube spacers, bolt & nut
9	AIR SPRING PLATE			
	HT300YB.XXX	S-23294	2	For Dual Combo Stud A/S
		S-21209	2	For Single Combo Stud A/S
	HT300YB-XX-XXX	A-24966	2	For A/S with 1 combo & 1 std. Stud.
10	AIR SPRING			
	HT300YB.XXX	S-25319	2	Dual Combo Stud A/S
		S-20414	2	Single Combo Stud A/S
	HT300YB-XX-XXX	S-3830	2	A/S with 1 Combo & 1 std Stud.
11	AIR SPRING BOLT KIT			
	HT300YB.XXX	S-25339/2	2	For Dual Combo Stud A/S
		S-20033/2	2	For Single Combo Stud A/S
	HT300YB-XX-XXX	S-1981/2	2	For A/S with 1 Combo & 1 std Stud.
12	UPPER SHOCK CLEVIS			
	HT300YB.XXXX	S-20113	2	
	HT300YB-XX-XXX	S-2592	2	
13	SHOCK ABSORBER	S-20002	2	
14	SHOCK BOLT KIT	S-2157/2	2	
15	LOWER SHOCK CLEVIS (Not Shown)			
	Standard, roadside	S-20145-1	1	
	Standard, curbside	S-20145-2	1	
16	SHOCK STRAP KIT (Not Shown)			
	For A-20002 shock absorber	S-14587-1	1	

NOTE: US/YB can be identified by Dual Combo Stud A/S & YB "dot number" YB.XXX

NOTE: UB/YB only consists of two part numbers HT300YB-7.5-001 or HT300YB-9-001

*Actual product performance may vary depending upon vehicle configuration, operation, service and other factors.
All applications must comply with applicable Hendrickson specifications and must be approved by the respective vehicle manufacturer with the vehicle in its original, as-built configuration.
Contact Hendrickson for additional details regarding specifications, applications, capacities, and operation, service and maintenance instructions.*

Call Hendrickson at 866.RIDEAIR (743.3247) for additional information.



www.hendrickson-intl.com

TRAILER COMMERCIAL VEHICLE SYSTEMS

2070 Industrial Place SE
Canton, OH 44707-2641 USA
866.RIDEAIR (743.3247)
Fax 800.696.4416

Hendrickson Canada ULC

2825 Argentia Road, Unit #2 - 4
Mississauga, ON Canada L5N 8G6
800.668.5360
905.789.1030 • Fax 905.812.9423

Hendrickson Mexicana

Circuito El Marqués Sur #29
Parque Industrial El Marqués
Pob. El Colorado, Municipio El Marqués,
Querétaro, México C.P. 76246
+52 (442) 296.3600 • Fax +52 (442) 296.3601

L1271 Rev B 04-23

© 2017 - 2023 Hendrickson USA, L.L.C. All Rights Reserved. All trademarks shown are owned by Hendrickson USA, L.L.C., or one of its affiliates, in one or more countries.
Information contained in this literature was accurate at the time of publication. Product changes may have been made after the copyright date that are not reflected.

Printed in United States of America